

RECLAMATION

Managing Water in the West

Lower Colorado River

**Challenges And Control Activities
For Invasive Mussels**



U.S. Department of the Interior
Bureau of Reclamation

Agenda

- Background – January 2007 adult quagga mussel found in Lake Mead (assumed to be from a mussel infested house boat)
- Fall of 2007 – Bureau of Reclamation lower Colorado Dams (LCDO) office completed facility review
- Findings from review and updated activities of the lower Colorado river dams
- Research activities and control barriers that are environmentally friendly
- Reclamation costs

RECLAMATION

Lake Mead, NV & Hoover Dam House Boat



RECLAMATION

Facility Assessments



RECLAMATION

Managing Water in the West

Facility Vulnerability Assessment Template

Invasive Quagga and Zebra Mussels

<http://www.usbr.gov/mussels/>



U.S. Department of the Interior
Bureau of Reclamation

May 2009

RECLAMATION


What Water Storage and Delivery Facilities are Vulnerable to a *Dreissena* Mussel Infestation?

Comparison of Zebra Mussel Colonization Potential with Environmental Tolerances

Variable	Colonization Potential (Infestation Probability)			
	High	Moderate	Low	Very Low
Salinity, ppm	0-1,000	1,000-4,000	4,000-10,000	10,000-35,000
Calcium, ppm	25-125	20-25	12-20	<7
pH	7.4-8.5	7.0-7.4	6.5-7.0	<6.5
		8.5-9.0		>9.0
Water temperature °C (°F)	17-25 (63-77)	25-27 (77-81)	15-17 (59-63)	<12 (<50)
Turbidity, cm (Secchi disk)	40-200	20-30	10-20	<10
			200-250	>250
Dissolved Oxygen, ppm	8-10	6-8	4-6	<4
Water velocity, (ft./sec.)	1.6-2.3	2.3-3.3	3.3-6.6	>6.6

RECLAMATION

Parker Dam



RECLAMATION

Sampling Plates at Parker Dam

November 11/07 – 6 Weeks of Settlement




RECLAMATION

Parker Dam Monitoring Plate Rope September 2008




RECLAMATION

Underwater Photo – Trash Rack Parker Dam - January 15, 2008



RECLAMATION

Underwater Photo – Domestic Water Intake Parker Dam



RECLAMATION

Spillway Gates – Parker Dam



RECLAMATION

the DAVIS DAM CONNECTION



RECLAMATION

Davis Dam Penstock Gate Oct.07




RECLAMATION

Drain Holes Plugged With Mussels




RECLAMATION

Generator Cooling Water Heat Exchanger Davis Dam Dec 2009




RECLAMATION

Hoover Dam Layout



RECLAMATION



Elev 1111
Dec 2007 Lake
Mead Level

Elev 1045
66'

Elev 970
141'

Elev 894
217'

RECLAMATION


Fore bay - 1094 ft

Intake - 1045 ft

Trash Racks –
6/2009

Upper Cylinder Gate -
11/2007


This close-up photograph shows a horizontal crack in a concrete slab. The crack is jagged and runs across the width of the slab. The concrete surface is rough and textured, with some areas showing exposed aggregate. A person's hand is visible in the upper right corner, holding a white object, possibly a piece of paper or a tool, near the crack.



RECLAMATION

Upper Nevada Penstock

October 2008



RECLAMATION

Observations from inspection of external surfaces – 10/2008

Penstock Lateral Shell Debris
(13ft diameter)



Over 6 Inches Deep

Penstock Drain – Heavy
Settling



RECLAMATION

Historical observations

**November 2007
Hoover Dam Penstock**

**Hoover Dam
Generator Cooling Water
Supply Line
April 2008**

**October 2008
Hoover Dam Penstock**

**October 2009
Hoover Dam Penstock**

10/22/2008

RECLAMATION

External Structures Options

Mechanical Cleaning



- de-water and use power wash
- underwater, scrape and vacuum or power wash

RECLAMATION

Oxidizing Chemical Treatment

- Chlorine
- Bromine
- Chlorine dioxide
- Chloramines
- Ozone
- Potassium permanganate




RECLAMATION

Lower Colorado Region Research Activities

- Monitoring substrate
- Installed bio-boxes
- Evaluating anti-foul coatings and materials to resist mussels (Dr. Allen Skaja, TSC Denver)
- Evaluating ultra-violet light treatment
- Testing 40 & 80 micro filtration systems
- Identifying and evaluating water jetting system for exterior cleaning
- Evaluation of bacterium (Zequanox) treatment
- Evaluating treatment alternatives (Redear Sunfish, sparker, chemical, thermal, biological)

RECLAMATION

Installed Bio-Box Sampler for Plant Monitoring



RECLAMATION

Coatings Panels Locations



RECLAMATION

Coatings Panels (cont.)



→
3-month
fouling rate



RECLAMATION



STEEL



ZINC - METALIZED



**ICI DEVOE
CATHACOAT 304**



**FUJI FILM SMART
SURFACES
4 MONTHS**



LUMINORE



**INTERNATIONAL
INTERSLEEK 970**

Fish Screen Material (Cu- Ni Wedge Wire)





3-month fouling
(Sept. – Dec. 2009)



RECLAMATION

Unit Cooling Water - Current Layout and New Design

UV design lower right corner



New design uses pumps using tail bay water supply instead of fore bay at Hoover Dam

RECLAMATION

Ballast Safe Filter Housing Parker Dam - November 2008



40 & 80 micron filter cartridge
inside of housing

RECLAMATION

Self Cleaning Ballast Safe Filter




Pre-strainer (filter)



Filter Cartridge – 40 micron


RECLAMATION

Domestic Water Intake – Davis Dam



RECLAMATION

Domestic Water Lines – Davis Dam



Ready for *Pseudomonas Fluorescens* Study

RECLAMATION

Water Jetting Equipment



Video

- pre inspection
- water jetting
- post inspection



RECLAMATION

Emerging Options - Zequanox *Pseudomonas fluorescens* (PF)



Mussels' last meal - Scientists want to add PF that are lethal to invasive mollusks to water at Hoover or Davis dams

RECLAMATION

Pseudomonas fluorescens Trials Davis Dam - March 2009



RECLAMATION

Emerging Options

- Bacterial product (Developed at NY State Museum and commercially developed by Marrone Organic Innovations), zebra mussel specific chemical....being tested on Quagga now
- How does it work?

The bacteria produce natural compounds that kill the mussels when ingested. It destroys the mussels' digestive system.



New York State Museum




RECLAMATION



What is a Sparker?

- High voltage spark between electrodes in water
- Vaporizes water, producing:
 - pressure pulse
 - light pulse
 - vapor-filled “bubble”
- The bubble oscillates
- Generate “sparks” at controlled intervals




4



Reflector Can Direct the Pressure

- Parabolic reflector with pressure generated at the focus directs pressure into pipe



7




How Does Pressure Control Zebra Mussels?

- Repeated pressure pulses create a hostile environment
 - Causes shells to close, preventing feeding
 - Mortality from mechanical damage at short range
 - Prevents larvae (veligers) from remaining in water column
 - Paper to be published in April AWWA Journal

8

RECLAMATION

Redear Sunfish, a.k.a. “Shell Cracker”



RECLAMATION

Aquatic Weeds – Lake Havasu, AZ August 2008



RECLAMATION

Reclamation expenditures

FY 08, 09, 10 and ARRA funding

Reclamation Costs and Budget for Quagga/Zebra Mussels	Total (rounded to near decimal)
Prevention	\$ 770 K
Early Detection/Rapid Response	\$ 5.3 M (ARRA Funding \$ 4.5 M)
Control and Management	\$ 1.7 M
Research	\$ 3.5 M
Education and Outreach	\$ 1.2 M
Total	\$ 12.59 M

RECLAMATION

RECLAMATION

Managing Water in the West

Questions

Leonard Willett
Quagga Mussel Coordinator
(702) 494-2216
LWillett@usbr.gov



U.S. Department of the Interior
Bureau of Reclamation